

08/942005 300 304 Maestro Central - MINE Mindow (File) Gererell . ide Accelers 302 NetworkMap Sever Name Real Museum MIN WINE Aleit Windows 医回图 Uka Oplas . Briegerick include i Newskilled ⊕-- ≝ MINE ZMINE ...

F19. 3




FIG. SA

08/9/2085

ALERT/TYPE

Displayed Description

CPU

CPU identified by the CPU Number failed because of high

temperature and/or low power

SYSTEM BOARD FAN

The speed of the system board fan identified by the Cooling Fan Number has dropped below the minimum limit.

TEMPERATURE SENSOR

The temperature of the system board fan identified by the temperature sensor number has dropped below the minimum limit.

POWER SUPPLY

Power Supply identified by the Power Supply Number has been extracted or inserted or has gone into an abnormal state, please look into the Help file for more detail

ADAPTER

The adapter identified by the Adapter Number or its driver is malfunctioning.

CANISTER

The Canister identified by the Canister Number has either

been extracted or inserted.

SLOT FAN

The speed of the I/O slot fan identified by the Slot Fan Number has dropped below the minimum limit

(slotFanMinSpeed).

CANISTER FAN

The speed of a fan in the canister identified by the Canister Number has dropped below the minimum limit.

08/942005

ALERT/TYPE

Displayed Description

CPU

CPU identified by the CPU Number failed because of high temperature and/or low power

SYSTEM BOARD FAN

The speed of the system board fan identified by the Cooling Fan Number has dropped below the minimum limit.

TEMPERATURE SENSOR

The temperature of the system board fan identified by the temperature sensor number has dropped below the minimum limit.

POWER SUPPLY

Power Supply identified by the Power Supply Number has been extracted or inserted or has gone into an abnormal state, please look into the Help file for more detail

ADAPTER

The adapter identified by the Adapter Number or its driver is malfunctioning.

CANISTER

The Canister identified by the Canister Number has either

been extracted or inserted.


SLOT FAN

The speed of the I/O slot fan identified by the Slot Fan Number has dropped below the minimum limit

(slotFanMinSpeed).

CANISTER FAN

The speed of a fan in the canister identified by the Canister Number has dropped below the minimum limit.



F14.5

08/942005

		607	606	608	600	61Z 614
Maestro C	ലിരി	· [Log Window]		*************		
		Virdow Heb				[61]
ii o ii o		/		7		
		/				
(er Lama		Dac/Int	Source			Details
baba	1	11:29:16 AM Thu. September 4, 1997	Slot Fan Alert	serious	The speed of the I/O slot fan i	Please ch
baba	2	11:29:17 AM Thu. September 4, 1997	Slot Fan Alert	serious	The speed of the I/O slot fan i	Please ch
baba	3	11:34:38 AM Thu. September 4, 1997	Slot Fan Alert	serious	The speed of the I/O slot fan i	Please ch
baba	4	11:34:39 AM Thu. September 4, 1997	Slot Fan Alert	serious	The speed of the I/O slot fan i	Please ch
baba	5	11:36:36 AM Thu. September 4, 1997	Slot Fan Alert	serious	The speed of the I/O slot (an i	Please ch
baba	6	11:36:38 AM Thu. September 4, 1997	Slot Fan Alert	serious	The speed of the I/O slot fan i	Please ch
baba	7	2:04:27 PM Thu. September 4, 1997	Power Supply Alert	serious	Power Supply identified by the	Please ch
baba	8	2:05:14 PM Thu. September 4, 1997	Power Supply Alert	serious	Power Supply identified by the	Please ch
baba	9	2:05:17 PM Thu. September 4, 1997	Power Supply Alert	serious	Power Supply identified by the	Please ch
baba	10	2:05:18 PM Thu. September 4, 1997	Power Supply Alert	serious	Power Supply identified by the	Please ch
ba ba	11	2:06:36 PM Thu. September 4, 1997	Power Supply Alert	serious	Power Supply identified by the	Please ch
ba ba	12	2:07:35 PM Thu. September 4, 1997	Power Supply Alert	serious	Power Supply identified by the	Please ch
baba	13	2:07:36 PM Thu. September 4, 1997	Power Supply Alert	serious	Power Supply identified by the	Please ch
baba	14	2:07:37 PM Thu. September 4, 1997	Power Supply Alert	serious	Power Supply identified by the	Please ch
baba	15	2:08:49 PM Thu. September 4, 1997	Power Supply Alert	serious	Power Supply identified by the	Please ch
baba	16	2:09:28 PM Thu. September 4, 1997	Power Supply Alert	serious	Power Supply identified by the	Please ch
baba	17	3:01:10 PM Thu. September 4, 1997	Power Supply Alert	serious	Power Supply identified by the	Please ch
baba	18	3:01:27 PM Thu. September 4, 1997	Power Supply Alert	serious	Power Supply identified by the	Please ch
baba	19	6:36:25 PM Thu. September 4, 1997	Slot Fan Alert	serious	The speed of the I/O slot fan i	Please ch
baba	20	6:36:35 PM Thu. September 4, 1997	Slot Fan Alert	serious	The speed of the I/O slot fan i	Please ch
baba	21	6:44:04 PM Thu. September 4, 1997	Slot Fan Alert	serious	The speed of the I/O slot fan i	Please ch
baba	22 ·	6:44:06 PM Thu. September 4, 1997	Slot Fan Alert	serious	The speed of the I/O slot fan i	Please ch
baba	23	6:44:55 PM Thu. September 4, 1997	Slot Fan Alert	serious	The speed of the I/O slot fan i	Please ch
baba	24	6:44:57 PM Thu. September 4, 1997	Slot Fan Alert	serious	The speed of the I/O slot fan i	Please ch
baba	25	6:48:42 PM Thu, September 4, 1997	Slot Fan Alert	serious	The speed of the I/O slot (an i	Please ch

